



- A0 = LCD Enable (Out)
- A1 = LCD RS (Out)
- A2 = Servo1 izhod (Out)
- A3 = Servo2 izhod (Out)
- A4 = Tipka "MODE" (In)
- B0 = Tipka "minus-S1" (In)
- B1 = Tipka "plus-S1" (In)
- B2 = Tipka "minus-S2" (In)
- B3 = Tipka "plus-S2" (In)
- B4 = LCD Bit 4 (Out)
- B5 = LCD Bit 5 (Out)
- B6 = LCD Bit 6 (Out)
- B7 = LCD Bit 7 (Out)

Title		
Servotester z LCD prikazovalnikom		
Size	Number	Revision
A4		
Date:	30-Apr-2009	Sheet of
File:	F:\ADVSCH\LCD_TEST.SCH	Drawn By: B. Zupan